

FORT LAUDERDALE FLORIDA

CODE ENFORCEMENT BOARD HEARING AGENDA

OCTOBER 27, 2015 9:00 AM

CITY COMMISSION MEETING ROOM - CITY HALL 100 N ANDREWS AVENUE FT. LAUDERDALE, FL 33301

CODE ENFORCEMENT BOARD

Code of Ordinances: Sec. 11-3.

PURPOSE: Hear and decide cases in which violations are alleged of any provision of the Florida Building Code, Broward County Amendments and violations of the Code of Ordinances of the City of Fort Lauderdale when alleged together with a violation of the Florida Building Code.

Note: If any person decides to appeal any decision made with respect to any matter considered at this public meeting or hearing he/she will need a record of the proceedings and for such purpose, he/she may need to ensure that a verbatim record of the proceedings is made, which record includes the testimony and evidence upon which the appeal is to be based.

Board Members: Howard Elfman, Chair • Chad Thilborger, Vice Chair • Joan Hinton

- Howard Nelson Paul Dooley Lakhi Mohnani Patrick McGee
- Joshua Miron (alternate) Robert Smith (alternate) Michael Madfis (alternate)
- **Board Attorney:** Bruce Jolly

TWO OR MORE FORT LAUDERDALE CITY COMMISSIONERS OR MEMBERS OF A CITY OF FORT LAUDERDALE ADVISORY BOARD MAY BE IN ATTENDANCE AT THIS MEETING.

HEARING SCHEDULED

CASE NO: CE12101940

CASE ADDR: 2980 N FEDERAL HWY

OWNER: OB REAL ESTATE HOLDINGS 1692 LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

BOARD-UP OF OPENINGS WITHOUT A PERMIT.

FBC(2010) 105.4.18

INSTALLED FENCE AROUND BUILDING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 1604.1

STRUCTURAL SUPPORT FOR CONCRETE BALCONY HAS EITHER FAILED OR IT HAS BEEN REMOVED.

CASE NO: CE13061394 CASE ADDR: 6837 NW 29 AV

OWNER: US BANK NATIONAL ASSN TRSTEE % AMER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. THE OWNER ADDED A 2ND FLOOR BATHROOM ILLEGALLY.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE13070747 CASE ADDR: 1331 E LAKE DR

OWNER: 1331 E LAKE DRIVE LAND TR SAAVEDRA,

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THE SINGLE FAMILY DWELLING HAS BEEN ALTERED WITH THE COMPLETION OF AN OPEN AIR STRUCTURE WITHOUT A PERMIT.

WITHOUT A PERMIT

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15082171 CASE ADDR: 2841 SW 9 ST

OWNER: VERNEUS, ALPHONSINE H/E

GASTON, IBRAM JR ETAL

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DEN CONVERTED TO AN EFFICIENCY APARTMENT WITH A BATHROOM.

FBC(2014) 105.3.1.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILT A BATHROOM IN THE DEN WITHOUT ACQUIRING THE REQUIRED PERMITS.

FBC(2014) 105.3.1.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ALTERED THE ELECTRICAL SYSTEM IN THE COVERTED DEN TO EFFICIENCY WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINNING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. INSTALLED A CENTRAL A/C CONDENSOR UNIT WITHOUT THE REQUIRED PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A DUPLEX TO A FOURPLEX WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

1. CONVERTED DEN TO AN EFFICIENCY.

FBC(2014) 116.2.1.2.5

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE. IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

FIRE DAMAGE IN THE BUILDING IS A POTENTIAL LIFE AND SAFETY HAZARD SINCE THE BUILDING IS STILL ENERGIZED AND OCCUPIED.

CASE NO: CE15092059
CASE ADDR: 1544 NW 9 AVE
OWNER: KDE OF FL 1 LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS DWELLING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION OF A DUPLEX TO A FOURPLEX

WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING

DEPARTMENT.

FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. REMODELING AND ALTERATIONS TO THE STRUCTURE. WINDOWS, DOORS, WALLS, BATHROOMS REMODEL, KITCHEN REMODEL, PLUMBING.

FBC(2014) 105.19.2

THE BUILDING OFFICIAL AT HIS/HER DISCRETION SHALL INTERPRET THE BUILDING CODE AND COMPLIANCE REQUIREMENTS.

FBC(2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. STRUCTURAL MODIFICATIONS OF INTERIOR WALLS.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLATION OF DOORS AND WINDOWS.

FBC(2014) 105.3.1.4.4

ALTERING, REPAIRING, INSTALLATION OF PLUMBING COMPONENTS AND/OR MODIFYING THE PLUMBING SYSTEM AND ITS COMPONENTS WITHOUT OBTAINING THE REQUIRED PERMITS. INSTALLATION AND MODIFICATION BUT NOT LIMITED TO:

1. BATHROOM REMODEL WITH PLUMBING ALTERATIONS.

FBC(2014) 105.3.1.5

WHERE APPLICABLE PERMIT REQUIREMENTS MUST HAVE SUPPORTING DOCUMENTATION FROM A QUALIFIED DESIGN PROFESSIONAL.

FBC(2014) 105.4.1.2 OWNER RESPONSIBILITY.

FBC(2014) 109.3.3

THIS CODE CASE WILL REQUIRE ALL PERMITS TO BE DOUBLE FEE.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 115.1

STOP WORK ORDER ISSUED SINCE WORK IS ONGOING WITHOUT THE REQUIRED PERMITS.

FBC(2014) 116.1.2

THIS BUILDING IN ITS PRESENT CONDITION DOES NOT MEET THE CRITERIA OF THE FLORIDA BUILDING CODE FOR MINIMUM MAINTENANCE STANDARD AND THE FORT LAUDERDALE MINIMUM HOUSING CODE AND IT MUST BE REPAIRED BY THE OWNERS OR DEMOLISHED:

1. PER FLORIDA BUILDING CODE WORK WITHOUT PERMIT IS DEEMED TO BE UNSAFE.

CASE NO: CE14011733

CASE ADDR: 3114 NE 23 CT

OWNER: FUSSELL, GEORGE JR

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. CONSTRUCTED BOAT LIFT WITHOUT PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE14032107 CASE ADDR: 2006 NE 29 CT

OWNER: MARTIN, A LEE JR & LISA A

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. INSTALLED WINDOWS WITHOUT A PERMIT

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE14092255
CASE ADDR: 1231 NW 46 CT
OWNER: LANE, KENNETH R

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS, AS FOLLOWS:

1. THE DWELLINGS CARPORT HAS BEEN ENCLOSED INTO A

LIVING SPACE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14100967

CASE ADDR: 1760 LAUD MANORS DR

OWNER: ADIEL, RONNIE INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. REPLACED ROOF WITHOUT A PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15070101 CASE ADDR: 1649 NW 13 ST

OWNER: NOW HOME BUYERS LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

- 1. INTERIOR ALTERATIONS WITHOUT A PERMIT.
- 2. ELECTRICAL ALTERATIONS WITHOUT A PERMIT.
- 3. PLUMBING ALTERATIONS WITHOUT A PERMIT.
- 4. REROOFING/REPAIRS WITHOUT A PERMIT.
- 5. WINDOW INSTALLATION WITHOUT A PERMIT.
- 6. ROOF ALTERATIONS WITHOUT A PERMIT.
- 7. SHED WITHOUT PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15070227 CASE ADDR: 1032 NE 8 AV OWNER: ACOMB, JACK

ACOMB, LAWRENCE T

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

- 1. WOOD FENCE WITH NO PERMIT.
- 2. CONSTRUCTION OF AN ENCLOSURE WITH NO PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15070738

CASE ADDR: 1301 NE 2 AV

OWNER: SETTON, JOHN

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. RE-ROOFING WITH NO PERMIT.

FBC(2014) 105.3.1.4.10

REQUIREMENTS FOR ROOF PERMIT.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED WINDOWS WITHOUT PERMIT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVER-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

._____

CASE NO: CE15070923 CASE ADDR: 216 ROSE DR

OWNER: CECERE, LEONARD & MARY M

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. INSTALLED CANOPY AND ANCHORED TO BUILDING WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ENCLOSED CARPORT AND CONVERTED INTO GARAGE WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.15

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED WINDOWS AT CARPORT ALTERATION WITHOUT A PERMIT.

FBC(2014) 105.3.1.4.17

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED GARAGE DOOR TO CONVERTED CARPORT.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE14120163 CASE ADDR: 5920 NE 21 RD OWNER: SOUA, MOUEZ H/E

SOUA, MAHER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

POI NOI LIMITED 10:

- ENCLOSED CARPORT AND CONVERTED TO GARAGE.
 REPLACED WINDOWS AND DOORS FRONT ELEVATION.
- 3. INSTALLED GARAGE DOOR.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15060634
CASE ADDR: 1206 NW 16 CT
OWNER: RHA 2 LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. RENOVATION OF THE KITCHEN, NEW EXTERIOR DOORS AND A/C.

FBC(2010) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINNING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. A/C CHANGE OUT.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. DRAIN AND SUPPLY LINE FOR KITCHEN CABINETS.

FBC(2010) 105.4.5

THE ELECTRICAL IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. KITCHEN COUNTER OUTLETS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15061690
CASE ADDR: 3341 NE 42 CT
OWNER: BIELEN, ARVIN N

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. BUILDING STRUCTURES IN BACKYARD AND/OR BACK OF PROPERTY WITHOUT OBTAINING BUILDING PERMITS AS REQUIRED BY THE FLORIDA BUILDING CODE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15061969
CASE ADDR: 1613 NW 14 ST

OWNER: SWAY 2014-1 BORROWER LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. INSTALLED CENTRAL AIR CONDITIONER.

- 2. ELECTRICAL WORK FOR CENTRAL AC DISCONNECT.
- 3. INSTALLED WATER HEATER.
- 4. INTERIOR REMODELING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15060950 CASE ADDR: 2400 NW 55 CT

OWNER: NIPRO DIAGNOSTICS INC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.4.5

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. ELECTRICAL WORK DONE. A CHARGING STATION WAS

BUILT FOR THE ELECTRICAL CARS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE12120316

CASE ADDR: 3400 GALT OCEAN DR # 2107S

OWNER: FISCHER CORP INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH AN INTERIOR RENOVATION COMPLETED WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS

CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE12121552

CASE ADDR: 2175 NE 56 ST # 115 OWNER: GIOVANELLI, CHRISTOPHER

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS HAD AN INTERIOR REMODELING WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW

AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS

CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE14070534

CASE ADDR: 200 S BIRCH RD # 814
OWNER: SCHILLIZZI, LANCE
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH AN INTERIOR RENOVATION WITHOUT THE REQUIRED PERMITS $\mbox{\sc And/OR}$

INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW

AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.
SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND
PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS

CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15010907
CASE ADDR: 2718 NE 21 TER
OWNER: BROCKNER, MICHAEL
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH A DRIVEWAY

REPLACEMENT WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, SCHEDULE AND PASS ALL REQUIRED INSPECTIONS, AND PROPERLY CLOSE OUT ALL REQUIRED PERMITS TO FULLY COMPLY AND CLOSE THIS CODE CASE.

CASE NO: CE15020935

CASE ADDR: 2170 NE 51 CT # A9
OWNER: GUILDFORD, JOHN D
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH AN INTERIOR RENOVATION WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, SCHEDULE AND PASS ALL REQUIRED INSPECTIONS, PROPERLY CLOSE OUT ALL THE REQUIRED PERMITS TO FULLY COMPLY AND CLOSE THIS CODE CASE.

CASE NO: CE15030470
CASE ADDR: 201 NE 16 AV
OWNER: HINDS, KEVIN &
LAYNE, PAUL J

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH STRUCTURAL ALTERATIONS DONE WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS. THIS WORK INCLUDES BUT IS NOT LIMITED TO:

- 1. SECOND BATHROOM INSTALLED.
- 2. ROOMS SUB-DIVIDED WITH INTERIOR WALLS TO CREATE NEW ROOMS.
- 3. WOOD DECK WITH A WOOD PRIVACY SCREEN.

FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF PLUMBING WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS WHICH INCLUDES BUT IS NOT LIMITED TO:

1. A SECOND BATHROOM INSTALLED WITH A SHOWER, TOILET AND SINK.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF ELECTRICAL WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS THAT INCLUDES BUT IS NOT LIMITED TO:

1. ELECTRICAL INSTALLED IN THE SECOND BATHROOM AND OTHER CREATED ROOMS.

FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF NEW WINDOW AND DOORS WITHOUT THE REQUIRED PERMITS AND OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY UNDER F.B.C. 109.3.3

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15081042

CASE ADDR: 441 S FTL BEACH BLVD OWNER: SOPHIA ENTERPRISES INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH STRUCTURAL ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

- 1. THE COMPLETE BUILD-OUT OF A RESTAURANT.
- 2. NEW WINDOWS AND DOORS.
- 3. INTERIOR ALTERATIONS WITHOUT THE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH PLUMBING ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

1. PLUMBING FIXTURES INSTALLED WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH ELECTRICAL ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

- 1. ALARM CONTROL PANEL.
- 2. LIGHTING.
- 3. ELECTRICAL CONDUIT, ELECTRICAL DISCONNECTS, LOW VOLTAGE INSTALLED WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS COMMERCIAL BUILDING SPACE HAS BEEN ALTERED WITH MECHANICAL ALTERATIONS WHICH INCLUDE BUT ARE NOT LIMITED TO:

1. NEW A/C MECHANICAL UNITS AND DUCT WORK INSTALLED WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

THIS CODE CASE AND THE WORK DONE IN THIS
COMMERCIAL BUILDING SPACE WILL REQUIRE
ARCHITECTURAL DRAWINGS PREPARED BY A DESIGN
PROFESSIONAL TO INCLUDE ALL OF THE VIOLATIONS THAT
NEED TO BE PROPERLY PERMITTED, CORRECTED AND
INSPECTED AS REQUIRED BY THE FLORIDA BUILDING CODE.

FBC(2014) 109.3.3

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15081970 CASE ADDR: 5300 NE 24 TER

OWNER: CROSS FOX CONDO ASSN INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH A STRUCTURE BUILT IN THE POOL AREA WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 110.6

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY. SCHEDULED AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15091850

CASE ADDR: 200 S BIRCH RD # 1011
OWNER: FRENI MEHTA REV TR
MEHTA, FRENI TRSTEE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH A COMPLETE RENOVATION WHICH INCLUDES BUT IS NOT LIMITED TO:

- 1. WINDOWS AND DOORS BEING REPLACED.
- 2. FULL KITCHEN REMODEL TO INCLUDE THE FRAMING DOWN OF THE KITCHEN CEILING AND INSTALLING DRYWALL.
- 3. FULL BATHROOM RENOVATION WITH INSTALLATION OF DRYWALL/TILE BACKING BOARD.

 THIS WORK HAS BEEN PERFORMED WITHOUT HE REQUIRED STRUCTURAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INSTALLATION AND ALTERATIONS OF THE PLUMBING SYSTEM WHICH INCLUDE BUT IS NOT LIMITED TO:

- 1. INSTALLED A TANKLESS WATER HEATER.
- 2. CONVERTED THE TUB INTO A SHOWER.
- 3. REPLACED THE SHOWER VALVE.
- 4. REMOVED AND REPLACED ALL THE PLUMBING FIXTURES IN BOTH THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INSTALLATION AND ALTERATIONS OF THE ELECTRICAL SYSTEM WHICH INCLUDES BUT IS NOT LIMITED TO:

1. WIRING, OUTLETS, SWITCHES, DEVICES AND THE WIRING OF A TANKLESS WATER HEATER.

FBC(2014) 107.1.1

BECAUSE OF THE COMPLEXITY, SEVERITY, LIFE SAFETY ISSUES AND POTENTIAL LIABILITY TO THIS CONDO UNIT AND THE CONDO BUILDING, PROFESSIONAL DRAWINGS PREPARED BY A DESIGN PROFESSIONAL WILL BE REQUIRED TO ADDRESS EACH VIOLATIONS AND THE PROPER METHOD TO WHICH THE VIOLATIONS ARE TO BE CORRECTED.

FBC(2014) 109.3.3

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES OR POSSIBLY QUADRUPLE FEES THAT WILL BE APPLY.

FBC(2014) 110.6

SCHEDULED AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED.

CASE NO: CE15092005

CASE ADDR: 1800 N ANDREWS AVE # 05K

OWNER: LUTHY, HEDY

A & H LUTHY REV LIV TR ETAL

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WHICH INCLUDES

BUT IS NOT LIMITED:

1. THE COMPLETE DEMOLITION OF THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED STRUCTURAL PERMIT

AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS HAD PLUMBING ALTERATIONS PERFORMED WHICH INCLUDE BUT IS NOT LIMITED TO:

1. REMOVAL OF PLUMBING FIXTURES IN THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS HAD ELECTRICAL ALTERATIONS PERFORMED WHICH INCLUDES BUT IS NOT LIMITED TO:

1. THE REMOVAL OF THE CIRCUITS IN THE ELECTRICAL PANEL AND THE REMOVAL OF ALL THE ELECTRICAL DEVICES THROUGHOUT THIS CONDO UNIT WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 109.3.3

THE CONDO UNIT WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT WILL APPLY.

FBC(2014) 110.6

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE14020284

CASE ADDR: 821 N VICTORIA PARK RD

OWNER: 821 NORTH VICTORIA PARK RD LLC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THE MULTI-RESIDENTIAL PROPERTY HAS BEEN ALTERED WITH THE REPAVING OF THE PARKING LOT WITHOUT A

PERMIT.

CASE NO: CE14101642 CASE ADDR: 921 NE 16 TER

OWNER: COMMUNITY 8 PROPERTIES LLC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

WORK W/O PERMITS.

1. REPLACING KITCHENS.

2. CENTRAL A/C.

3. INSTALLING WOOD FENCE.

4. THERE ARE THREE ELECTRIC METERS ON THE PROPERTY. THEY NOW HAVE TURNED IT INTO A SIX UNIT PROPERTY. ALL THE PERMITS WERE VOIDED. SOME ARE EXPIRED WITH INSPECTIONS AND NOW THEY ARE WORK WITHOUT PERMITS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15011303
CASE ADDR: 1400 SW 29 TER
OWNER: QUINTERO, SONIA
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. INSTALLATION OF NEW WOOD FENCE AND GATES.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15032151 CASE ADDR: 1119 NE 6 AV

OWNER: EURAMIL, ARNOLD & SUZETTE G

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. PARKING AREA RESURFACE AND RESTRIPED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15042036

CASE ADDR: 3209 NE 36 ST # 4B OWNER: MIGA, PATRICIA ANN T &

EK. MIGA, FAIRICIA ANN I

MIGA, STEVEN J

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER:

1. REAR PATIO ENCLOSURE INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

THE TERMITIENC TROCEDS.

CASE NO: CE15061198
CASE ADDR: 1616 SE 2 CT
OWNER: FINN, ZACHARY
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. PAVERS INSTALLED ON DRIVEWAY AND SWALE AREA.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING PROCESS.

CASE NO: CE15062080

CASE ADDR: 4881 NW 9 TER

OWNER: CHARLES, ANNEMISE

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

WINDOW OPENING WAS ENCLOSED.
 CENTRAL A/C UNIT WAS REPLACED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15062105 CASE ADDR: 111 SW 8 AVE

OWNER: WONG, KATHERINE IRENE

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. THE WINDOWS ARE BEING REPLACED AT THE DWELLING.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15010557
CASE ADDR: 1521 NW 8 AVE

OWNER: 1519 NW 8 AVE LLC INSPECTOR: FRANK ARRIGONI

VIOLATIONS: FBC 105.1

- 1. THE EXTERIOR WALL BEHIND THE A/C COMPRESSORS HAS BEEN ALTERED WITHOUT PERMITS CREATING AN UNSAFE CONDITION.
- 2. AT LEAST 1 OF THE KITCHENS HAS HAD THE CABINETS REPLACED WITHOUT A PLUMBING OR ELECTRICAL PERMIT.
- 3. THE WATER HEATER HAS BEEN REPLACED.
- 4. AT LEAST ONE BATHROOM SINK HAS BEEN REPLACED. ADDITIONAL VIOLATIONS MAY EXIST.

FBC(2010) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. A/C COMPRESSOR.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

....

CASE NO: CE15090195 CASE ADDR: 3201 NE 19 ST

OWNER: YOUNG, PAUL A & DEBRA LORRAINE

INSPECTOR: FRANK ARRIGONI

VIOLATIONS: FBC(2014) 105.3.2.1

THE FOLLOWING PERMIT(S) WERE LEFT TO EXPIRE AND THE WORK IS IN PROGRESS AND/OR COMPLETED. THIS IS A LIFE SAFETY HAZARD. WORK COMPLETED HAS NOT PASSED THE FINAL INSPECTION TO COMPLY WITH THE FLORIDA BUILDING CODE REQUIREMENTS OF SECTION 110. AND IS DEEMED TO BE UNSAFE UNDER FLORIDA BUILDING CODE SECTION 116.2.1.3.1.:

- 1. BUILDING PERMIT #08042020 (NEW 2 STORY SFR: 4BED/4.5BATH, 2 CAR GARAGE).
- 2. MECHANICAL PERMIT #08042022 (INSTALL TWO NEW A/C UNITS. TOTAL OF 10 TONS).
- 3. PLUMBING PERMIT #09041265 (INSTALL 120-GAL A/G LP TANK WITH GAS LINE TO 3).

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15020614 CASE ADDR: 2621 NW 18 CT

OWNER: COOKIES & CRACKERS CORP

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.4.18

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

1. A WOOD FENCE WITH TWO GATES HAS BEEN ERECTED ON

THE PROPERTY.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15041750
CASE ADDR: 2456 NE 27 TER
OWNER: BILLITIER, DAVID
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.4.8

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. AN AWNING WAS ERECTED IN FRONT OF THE GARAGE AND SEVERAL AWNINGS WERE PLACED ABOVE THE OPENING OF THE DWELLING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15081479

CASE ADDR: 520 NE 12 AV

OWNER: QUINTAS, FRANK

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2014) 105.3.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE AND THE POOL CONSTRUCTION WAS FINISHED. TODAY IT REMAINS WORK WITHOUT PERMITS. IT IS A LIFE SAFETY VIOLATION DUE TO THE FACT THAT THE ELECTRICAL SYSTEM HAS NOT BEEN FINALED AND THE CHILD BARRIERS HAVE NOT BEEN APPROVED TO COMPLY WITH THE FLORIDA CHILD PROTECTION ACT FS515.

- 1. BUILDING PERMIT #00070011 (BUILD POOL 12 X 24).
- 2. ELECTRICAL PERMIT# 00070015.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

RETURN HEARING (OLD BUSINESS)

CASE NO: CE13021763

CASE ADDR: 1200 CITRUS ISLE OWNER: LAZARIDI, ALLEN INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED BY A REMODELING PROJECT THAT INCLUDES BUT IS NOT LIMITED TO THE FOLLOWING WORK WITHOUT A PERMIT:

1. CARPORT ENCLOSED.

2. NEW WINDOWS HAVE BEEN INSTALLED.

- 3. NEW EXTERIOR DOORS HAVE BEEN INSTALLED.
- 4. NEEDS PERMIT FOR ELECTRICAL WORK TO THE DOCK.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14101440 CASE ADDR: 2000 SW 4 AVE

OWNER: J R MANAGEMENT GROUP LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS.

A STOP WORK ISSUED FOR:

- 1. THE OPENING PROTECTIONS WERE REPLACED AT THE DWELLING.
- 2. THE OUTSIDE WALLS AND CEILING IN THE CARPORT AND PORCHES BELONGING TO THE PROPERTY ARE BEING STUCCOED.
- 3. THE INTERIOR WALLS HAVE BEEN GUTTED AND THERE IS WORK IN PROGRESS ON THE ELECTRICAL AND PLUMBING SYSTEM TO UPGRADE THEM.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 115.1

A STOP WORK WAS ISSUED.

CASE NO: CE14072224
CASE ADDR: 3621 SW 22 ST
OWNER: MARTIN, IDANIA
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOWS:

- 1. THE OWNERS OF THIS PROPERTY HAVE REMOVED A CHAIN LINK FENCE BELONGING TO 3620 SW 21 CT AND REPLACED IT WITH A WOOD FENCE.
- 2. THEY BUILT A SHED TO HOUSE LARGE DOGS AND IS ATTACHED TO THE WOODEN FENCE.
- 3. BETWEEN 2007 AND 2008 A STORAGE SHED WAS INSTALLED.
- 4. BETWEEN 2011 AND 2012 A SLAB ON GRADE WAS DONE ON THE WESTSIDE OF THE PROPERTY LOT.
- 5. IN 2012, WOOD FENCES WITH GATES WERE ERECTED ON BOTH SIDES OF THE PROPERTY FRONT FACING SOUTH.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14110356
CASE ADDR: 2612 BARBARA DR
OWNER: MONDANI, GLEN H/E
MONDANI, PENTELOPE

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT. STOP WORK ISSUED.

THERE IS WORK IN PROGRESS WITH EXPIRED PERMITS:
1. COMPLETED RENOVATION INSIDE OF THE DWELLING.

- 2. AN ELECTRICAL GENERATOR WITH GAS OR LP SUPPLIED
 TO IT WAS INSTALLED. THREE GAS SUPPLY LINES RAN TO
- 3. THE GARAGE WAS DEMOLISHED AND A SERVANT'S QUARTERS WAS BUILT WITH ELECTRICAL AND PLUMBING ALTERATIONS.
- 4. HURRICANE SHUTTERS WERE INSTALLED.
- 5. AN EXTERIOR DOOR WAS REPLACED.

THE INTERIOR OF THE HOUSE.

- 6. ALTERATIONS TO THE FRONT PORCH.
- 7. PAVERS IN THE DRIVEWAY WERE DONE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15041067 CASE ADDR: 2816 NE 20 CT

OWNER: BOSSART, CYNTHIA L

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE. THE POOL WAS FINISHED AND TODAY IT REMAINS WORK WITHOUT A PERMIT. THERE ARE ALSO LIFE SAFETY VIOLATIONS BECAUSE THE ELECTRICAL SYSTEM HAS NOT BEEN FINALLED AND THE CHILD BARRIERS HAVE NOT BEEN APPROVED.

1. MECHANICAL PERMIT #08090768 (MDUCT)

2. BUILDING PERMIT #03072131 (BWINDOWS)

3. BUILDING PERMIT #05030721 (BALTR1M)

4. ELECTRICAL PERMIT #05030915 (EPOOL/SPAR)

5. BUILDING PERMIT #05030912 (BPOOL/SPAR)

6. ELECTRICAL PERMIT #06030142 (ERESADD)

7. PLUMBING PERMIT #08070837 (PIPINGREP)

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14110452 CASE ADDR: 1729 NW 16 AVE

OWNER: CUKIERKORN, JACQUES

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT.

STOP WORK ISSUED

1. INTERIOR ALTERATIONS IN THE KITCHEN AND BATHROOMS AREAS. BOTH WERE GUTTED.

2. FRAME AND DRYWALL WORK BEING DONE WITH NEW PLUMBING AND ELECTRIC FIXTURES.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15041939

CASE ADDR: 1140 N FLAGLER DR
OWNER: TANGALAKIS, HARRY G

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. THIS BUILDING WAS APPROVED TO BE USED AS A WAREHOUSE. IT HAS BEEN ALTERED AND NOW IT IS A THEATRE. THEY HAVE AN OPEN AREA WITH A WOOD PLATFORM WITH CHAIRS TO SEAT OVER FIFTY PERSONS AND THIS WAREHOUSE IS NOW A VENUE FOR DRAMA OR COMEDY SHOWS.
- 2. A WOOD PLATFORM AREA WAS BUILT AT THE REAR TO BE USED FOR THE LIGHT AND MUSIC DIRECTOR.
- 3. THE PARKING LOT, THE MAIN ENTRANCE, THE HALLWAY LEADING TO THE SEATING AREA AND THE TWO EXISTING BATHROOMS ARE NOT THE STANDARD REQUIREMENT FOR THE ADA OR FBC ACCESSIBILITY.
- 4. THERE ARE FLAMMABLE MATERIALS THAT WERE USED IN THE CONSTRUCTION OF THE STAGE AND THE LIGHTS. STAGE LAMPS WERE HUNG OVER THE OPEN CEILING WITH THE USE OF ELECTRICAL EXTENSIONS CORDS. IN CASE OF A FIRE, THE FLAMES CAN FREELY MOVE FROM ONE AREA OF THE WAREHOUSE TO THE OTHER WITHOUT BEING STOPPED BY A FIRE PARTITION OR BARRIERS.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. ALTERATIONS WERE DONE TO THE ELECTRICAL SYSTEM TO POWER ALL THE LAMPS AND STAGE LIGHTS.
- 2. THE LIGHTS ARE BEING SUPPLIED FROM THE WALL OUTLETS WITH POWER OR EXTENSION CORDS. BY THIS ACTION THE OWNER IS INCREASING THE AMPERAGE LOAD IN THE MAIN ELECTRICAL PANEL OVER THE TOTAL AMPS LOAD RATING THAT WAS PERMITTED. IT HAS BECOME AN ELECTRICAL FIRE HAZARD.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THIS BUILDING HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION FOR GROUP M TO AN ASSEMBLY GROUP A-2 OR A-3; WITHOUT OBTAINING THE REQUIRED PERMITS FOR A CHANGE OF USE AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE15030848
CASE ADDR: 716 SW 16 ST

OWNER: DAUNTLESS PROPERTIES LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND C.O:

- 1. THEY ARE ENCLOSING THE CARPORT AND EXTENDING THE EXISTING ROOF OVER THE CARPORT TO ADD A BEDROOM & BATH TO THE REAR BUILDING.
- 2. A NEW ROOF WAS BUILT ON THE ADDITION.
- 3. PLUMBING AND ELECTRICAL ALTERATIONS WERE DONE TO BUILD A BATHROOM AND BEDROOM AT THE REAR.
- 4. BUILDING A KITCHEN AREA AND ALTERATIONS TO THE EXISTING ONE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE13030518

CASE ADDR: 1215 SEMINOLE DR OWNER: KEENAN, BRIAN F INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

INTERIOR REMODELING WITHOUT PERMITS.

CASE NO: CE14100227

CASE ADDR: 528 VICTORIA TER

OWNER: 528 VICTORIA TERRACE LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO THE ENCLOSURE OF THE GARAGE WITHOUT

THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED TO INCLUDE BUT IS NOT LIMITED TO THE INSTALLATION OF WINDOWS AND

DOORS WITHOUT THE REQUIRED PERMITS AND OR

INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, SCHEDULE AND PASS ALL REQUIRED

INSPECTIONS AND PROPERLY CLOSE OUT ALL THE

REQUIRED PERMITS TO FULLY COMPLY AND CLOSE THIS

CODE CASE.

CASE NO: CE14100302

CASE ADDR: 425 SEABREEZE BLVD OWNER: PHF OCEANFRONT LP

% FILLMORE CAPITAL PARTNERS

INSPECTOR: ROBERT MASULA

VIOLATIONS: 9-280(b)

THERE ARE BUILDING PARTS WHICH ARE DETERIORATED

AND NOT MAINTAINED:

THE WOODEN DOCK HAS NOT BEEN MAINTAINED AND HAS NOW DETERIORATED FROM THE ELEMENTS. THIS STRUCTURE HAS NOW BECOME A WINDSTORM HAZARD AND IS UNSAFE.

FBC(2010) 116.1.1

THE WOOD DOCK AND CONCRETE DOCK DECK HAS DETERIORATED TO THE POINT WHERE IT IS COLLAPSING AND HAS BECOME A HAZARD TO THE PROPERTY AND

WATERWAY.

FBC(2010) 116.2.1.2.2

THE WOOD DOCK AND CONCRETE DOCK DECK HAS DETERIORATED TO THE POINT WHERE IT NEEDS TO BE COMPLETELY DEMOED AND REMOVED OR REBUILT WITH THE

PROPER PERMITS FIRST BEING OBTAINED.

CASE NO: CE13031281

CASE ADDR: 2609 E LAS OLAS BLVD OWNER: BRANDT-ALBERT, MARIA M

MARIA M BRANDT-ALBERT REV TR

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

- 1. THIS PROPERTY HAS BEEN ALTERED WITH AN ADDITION BUILT ON THE EAST SIDE OF THE HOUSE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 2. THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF A CARPORT/AWNING STRUCTURE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 3. THIS PROPERTY HAS BEEN ALTERED WITH A DOCK STRUCTURE BUILT WITHOUT A PERMIT RECORD OR INSPECTION RECORD FOR THIS BOAT DOCK.

FBC(2010) 105.4.1

THIS PROPERTY HAS BEEN ALTERED WITH A PATIO ROOF STRUCTURE INSTALLED ON THE N.W. CORNER OF THE PROPERTY WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH ELECTRICAL WORK INSTALLED ON THE DOCK AND OTHER AREAS OF UNPERMITTED (ADDITIONS) WORK WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.8

THIS PROPERTY HAS BEEN ALTERED WITH AN AWNING INSTALLED ON THE WEST SIDE OF THE HOUSE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS AND PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE14110051 CASE ADDR: 2811 NE 57 ST

OWNER: DEUTSCHE BANK NATL TR CO TRSTEE

% FIDELITY/HSBC-NY

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE

INSTALLATION OF TWO BATTER PILINGS WITHOUT THE

REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS FOR THIS CODE CASE TO BE FULLY

COMPLIED AND CLOSED.

CASE NO: CE14110327
CASE ADDR: 433 NE 14 AVE
OWNER: BROOKS, SCOTT
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INTERIOR DEMOLITION AND REMODELING WITHOUT THE REQUIRED

PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE

IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15010123

CASE ADDR: 441 S FTL BEACH BLVD OWNER: SOPHIA ENTERPRISES INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE

INSTALLATION OF AN AWNING WITHOUT THE REQUIRED

PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15011493

CASE ADDR: 401 SW 4 AVE # 605

OWNER: TOTH, ILDIKO INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

- 1. THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE DEMOLITION OF THE KITCHEN AND TWO BATHROOMS WITHOUT THE REQUIRED PERMITS.
- 2. THIS CONDO UNIT HAS ALSO BEEN ALTERED WITH THE COMPLETE REMODELING OF THE ENTIRE UNIT WHICH INCLUDES BUT IS NOT LIMITED TO STRUCTURAL WORK BEING DONE WHICH INCLUDES BUT IS NOT LIMITED TO FRAMING, DRYWALL AND TILE BACKING BOARD WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE REMODELING OF THE UNIT WHICH INCLUDES BUT IS NOT LIMITED TO THE REMOVAL AND REPLACEMENT OF THE PLUMBING FIXTURES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE RENOVATION OF THE ENTIRE UNIT WHICH INCLUDES BUT IS NOT LIMITED TO ELECTRICAL WIRING BEING INSTALLED AND ALTERING THE EXISTING ELECTRICAL DEVICES AND SWITCHES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS CONDO UNIT HAS BEEN ALTERED WITH THE COMPLETE REMODELING OF THE KITCHEN AND BATHROOMS INCLUDING BUT NOT LIMITED TO THE ALTERATION OF THE MECHANICAL DUCT WORK AND FANS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS CODE CASE WILL FIRST REQUIRE THAT THE CONDO UNIT OWNER HIRE A LICENSED ARCHITECT OR ENGINEER TO PROVIDE A COMPLETE SET OF DRAWINGS TO ADDRESS ALL THE VIOLATIONS AND THE NEEDED CORRECTIONS. BECAUSE OF THE SEVERITY OF THE ELECTRICAL WORK THAT WAS DONE THIS WILL BE A REQUIREMENT IN ORDER TO OBTAIN PERMITS. THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL THE REQUIRED PERMITS, SCHEDULE AND PASS ALL THE REQUIRED INSPECTIONS, PROPERLY CLOSE OUT ALL THE REQUIRED PERMITS TO FULLY COMPLY AND CLOSE THIS CODE CASE.

CASE NO: CE15011800

CASE ADDR: 229 S FTL BEACH BLVD OWNER: EL-AD FL BEACH CR LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN AWNING DISPLAYING SIGNAGE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.8

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF AN ALUMINUM AWNING STRUCTURE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15011944 CASE ADDR: 609 NE 8 AV

OWNER: ELITE HOME PARTNERS LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH INTERIOR AND EXTERIOR RENOVATIONS WITHOUT THE REQUIRED PERMITS

AND/OR INSPECTIONS.

FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED WITH THE REPLACEMENT OF THE FRONT DOOR WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.17

THIS PROPERTY HAS BEEN ALTERED WITH THE REPLACEMENT OF THE GARAGE DOOR WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE OUT ALL REQUIRED PERMITS BEFORE THIS CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15020109

CASE ADDR: 2100 S OCEAN LA # 502

OWNER: PANE, BRIAN D INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH INTERIOR ALTERATIONS THAT COMPROMISED THE PARTY/FIRE WALL BETWEEN THE TWO UNITS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH INTERIOR ELECTRICAL ALTERATIONS WHERE ROMEX WIRING WAS INSTALLED. THIS WORK IS ILLEGAL IN A HI-RISE CONDO BUILDING AND DOES NOT MEET CODE. THIS WORK WAS DONE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS CONDO UNIT HAS BEEN ALTERED WITH INTERIOR MECHANICAL ALTERATIONS WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15020958

CASE ADDR: 3200 NE 36 ST # 411

OWNER: BAUCO, DOMENICO

BAUCO, MARISA

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.4.11

THIS CONDO UNIT HAS BEEN ALTERED WITH THE

INSTALLATION OF A MINI SPLIT A/C SYSTEM WITHOUT

THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE

INSTALLATION OF ELECTRICAL TO POWER A MINI SPLIT A/C SYSTEM WITHOUT THE REQUIRED PERMIT AND/OR

INSPECTIONS.

FBC(2010) 110.9

THE CONDO UNIT OWNER MUST OBTAIN ALL REQUIRED

PERMITS, SCHEDULE AND PASS ALL REQUIRED INSPECTIONS, AND PROPERLY CLOSE OUT ALL THE

REQUIRED PERMITS TO FULLY COMPLY AND CLOSE THIS

CODE CASE.

.-----

CASE NO: CE15021157 CASE ADDR: 1424 NE 55 ST

OWNER: GESTION D E Q INC INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE

RE-BUILDING OF A DOCK WITHOUT THE REQUIRED PERMIT

AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN THE REQUIRED PERMIT, SCHEDULE AND PASS THE REQUIRED INSPECTIONS, AND PROPERLY CLOSE OUT THE REQUIRED PERMIT TO FULLY COMPLY AND CLOSE THIS CODE CASE.

CASE NO: CE15040668

CASE ADDR: 619 N FTL BEACH BLVD

OWNER: SEA CLUB OCEAN RESORT HOTEL INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF A CONCRETE BLOCK WALL, WINDOWS, RAILING AND OTHER REMODELING WORK WITHOUT THE

REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15040732 CASE ADDR: 1032 NE 15 AVE

OWNER: YUTHASUNTHORN FAMILY ENTERPRISES INC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR AND EXTERIOR REMODELING WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.3

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR DEMOLITIONS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE ELECTRICAL WORK BEING DONE INCLUDING REPLACING THE ELECTRICAL PANEL WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15050611 CASE ADDR: 1416 NE 6 ST

OWNER: 1416 NE 6TH STREET LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE INTERIOR RENOVATION OF THE KITCHEN AND BATHROOMS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE PLUMBING FIXTURES AND GAS WATER HEATERS WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE ELECTRICAL PANELS, OUTLETS, SWITCHES AND DEVICES WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE GAS WATER HEATERS WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE AFTER THE FACT REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY.

SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15051433 CASE ADDR: 1728 NE 20 AVE

OWNER: CARL A HOLCOMB REV LIV TR

HOLCOMB, CARL A TRSTEE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER,

BUT NOT LIMITED TO:

1. A/C UNITS WERE INSTALLED.

2. KITCHEN CABINETS ARE BEING REPLACED WHICH REQUIRE PLUMBING PERMIT FOR SINK INSTALLATION AND ELECTRICAL PERMIT FOR GFI ON THE COUNTER.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. SINK INSTALLATION FOR KITCHEN CABINETS.

FBC(2010) 105.4.5

THE ELECTRICAL IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ELECTRICAL GFI FOR KITCHEN CABINETS AND ELECTRICAL FOR A/C UNITS.

FBC(2010) 105.4.11

THE MECHANICAL SYSTEM OF THE BUILDING HAS BEEN ALTERED OR CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO: 1. INSTALLATION OF DUCTLESS A/C UNITS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

CASE NO: CE15051943
CASE ADDR: 2848 NE 37 CT
OWNER: BLAKE, ROBERT K JR

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH INTERIOR ALTERATIONS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.18

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF A FENCE WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15061470
CASE ADDR: 1638 RIVER LN
OWNER: COMMISSO, HELEN

HELEN G MACALPINE REV TR

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR AND EXTERIOR REMODELLING BEING DONE WITHOUT THE REQUIRED STRUCTURAL PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE REMODELLING WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE INTERIOR AND EXTERIOR REMODELLING BEING DONE WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS PROPERTY HAS BEEN ALTERED WITH EXTENSIVE REMODELLING BEING DONE WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15080187

CASE ADDR: 2933 POINSETTIA ST

OWNER: CORTEZ PROPERTY DEV LLC

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 116.1.1

- 1. THERE ARE LIGHT FIXTURES MISSING IN THE WALKWAYS AND STAIRWELLS OF THIS BUILDING. THIS IS A VIOLATION UNDER THE MINIMUM HOUSING CODE.
- 2. THERE ARE UNITS IN THIS BUILDING WHERE THE KITCHENS AND BATHROOMS HAVE BEEN PARTIALLY DEMOLISHED OR COMPLETELY DEMOLISHEDED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS IS ALSO A VIOLATION UNDER THE MINIMUM HOUSING CODE.
- 3. THE STAIRWELL ON THE NORTH END OF THE BUILDING LEADING TO THE ROOFTOP AREA HAS BEEN CLOSED OFF, FRAMED, SHEATHING AND STUCCOED OVER WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 4. THERE ARE RENTAL UNITS IN THIS BUILDING THAT HAVE HAD KITCHENS AND BATHROOMS REMODELED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.
- 5. THE LOW VOLTAGE ELECTRICAL BOX ON THE GROUND FLOOR IN THE GARAGE AREA IS IN DISREPAIR. WIRING IS EXPOSED AND HANGING LOOSE. THIS IS AN ELECTRICAL CODE VIOLATION AND A MAINTENANCE VIOLATION.
- 6. THERE ARE ILLEGAL FIRE DOORS THAT HAVE BEEN INSTALLED IN THE STAIRWELLS AND THE ENTRY DOORS OF THE UNITS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THIS IS ALSO A FIRE CODE VIOLATION.
- 7. THE ILLEGAL UNIT ON THE ROOFTOP HAS A PATIO AREA WHICH HAS NO BALCONY RAILING IN PLACE AND IS A FOUR STORY DROP. THIS IS A LIFE SAFETY ISSUE.
- 8. THERE ARE ELECTRICAL PANELS THAT HAVE NOT BEEN MAINTAINED AND ALSO HAVE MISSING BREAKERS. THIS IS AN ELECTRICAL CODE VIOLATION AND ALSO A POTENTIAL LIFE SAFETY ISSUE.
- 9. THERE ARE ELECTRICAL BOXES AND OUTLETS THAT ARE ROTTED OUT AND IN NEED OF REPLACEMENT. THIS IS AN ELECTRICAL CODE VIOLATION.
- 10. THERE ARE STAIRWELL DOORS WHICH THE DOOR CLOSERS DO NOT CLOSE THE DOOR PROPERLY AND THE DOORS THEMSELVES DO NOT CLOSE PROPERLY. THIS IS A MAINTENANCE AND FIRE CODE VIOLATION.

FBC(2014) 116.1.2

1. THERE IS AN ILLEGAL ROOF TOP ADDITION THAT IS CURRENTLY ADVISED AS A STUDIO RENTAL. THIS ILLEGAL ROOF TOP ADDITION WAS A CODE CASE FROM OCTOBER 22, 2002. PERMIT 03060376 WAS APPLIED FOR ON 06-05-2003, FAILED PLAN REVIEW. THE PERMIT WAS

NEVER ISSUED AND THE APPLICATION WAS PURGED FROM OUR SYSTEM ON NOVEMBER 21, 2003.

FBC(2014) 116.2.1.1.2

1. THERE IS AN UNWARRANTED ACCUMULATION OF DEBRIS AND OTHER COMBUSTIBLE MATERIAL WHICH INCLUDES BUT IS NOT LIMITED TO: COUCHES, FUEL CONTAINERS, SCREEN DOORS, ABANDONED VEHICLES, PAINT CANS AND LUMBER. THIS IS A POTENTIAL FIRE HAZARD.

FBC(2014) 116.2.1.1.3

- 1. NFPA 1:13.6.9.3.1.1.1 OUT FE 05/14

 TO WIT: THE FIRE EXTINGUISHER(S) HAS/HAVE NOT BEEN SERVICED AND TAGGED BY A STATE LICENSED COMPANY WITHIN THE PAST 12 MONTHS.
- 2. NFPA 101:7.9.2.1 SERVICE ALL EMERGENCY LIGHTS. TO WIT: THE EMERGENCY LIGHT DOES NOT ILLUMINATE AS DESIGNED.
- 3. NFPA 101:7.10.5.2.1 SERVICE ALL EXIT SIGNS. TO WIT: THE EXIT SIGN DOES NOT ILLUMINATE AS DESIGNED.
- 4. NFPA 1:10.11.6 REMOVE ALL GRILLS FROM STRUCTURE.

 TO WIT: A(AN) HIBACHI, GRILL, OR OTHER SIMILAR DEVICE(S) USED FOR COOKING, HEATING, OR ANY OTHER PURPOSE IS BEING USED OR KINDLED ON A BALCONY, UNDER AN OVERHANGING PORTION, OR WITHIN 10 FT (3 M) OF A STRUCTURE.
- 5. NFPA 1:1.7.6.2 FIX F/A REPAIR THE FIRE ALARM SYSTEM.

 TO WIT: THE FIRE ALARM SYSTEM APPEARS TO HAVE NO POWER AND IS NOT FUNCTIONAL AT THIS TIME. NO ACCESS TO THE ELECTRIC METER ROOM TO VERIFY THIS CONDITION. PROVIDE ACCESS.
- 6. NFPA 101:31.3.4.5.1 REPAIR ALL SMOKE DETECTORS.

 TO WIT: HARDWIRED SMOKE DETECTORS ARE NOT BEING MAINTAINED IN ACCORDANCE WITH NFPA 101:31.3.4.5.1.
- 7. NFPA 101:7.2.1.8.1 REPAIR ALL DOORS TO SELF? CLOSE AND LATCH.

 TO WIT: SELF CLOSING OR AUTOMATIC CLOSING DOOR(S) DON'T SELF CLOSE AND LATCH.

- 8. NFPA 101:7.2.1.8.1 REPAIR ALL FIRE RATED STAIRWELL DOORS.

 TO WIT: SELF CLOSING OR AUTOMATIC CLOSING DOOR(S) DON'T SELF CLOSE AND LATCH.
- 9. NFPA 1:11.1.2 REPAIR ALL EXPOSED WIRING. TO WIT: ELECTRICAL WIRING NOT PER NFPA 70, NATIONAL ELECTRICAL CODE.
- 10. NFPA 1:4.5.8.6 REPLACE / REPAIR ALL MISSING HAND RAILINGS.

 TO WIT: SAFEGUARDS, RAILING ARE MISSING AND HAVE BEEN REMOVED FROM THE 4TH FLOOR AND ARE NOT SECURED IN AREAS OF THE 3RD AND 2ND FLOOR.
- 11. 9999 UNSAFE BUILDING.

 TO WIT: THE BUILDING OFFICIAL OF THE CITY OF FORT LAUDERDALE HAS POSTED THIS PROPERTY AS AN UNSAFE STRUCTURE TODAY (TUESDAY AUGUST 4th, 2015).
- 12. NFPA 1:11.1.10 REPLACE ALL MISSING ELECTRICAL COVERS.

 TO WIT: THERE IS/ARE MISSING ELECTRICAL COVER(S).

FBC(2014) 116.2.1.2.1

- 1. THERE ARE BALCONY RAILINGS WHICH HAVE BROKEN FREE AND ARE NOW ATTACHED WITH ANGLE BRACKETS. THESE RAILINGS ARE LOOSE AND CAN EASILY BE BROKEN FREE CAUSING A FALL HAZARD AND IS A LIFE SAFETY ISSUE.
- 2. THERE ARE OVERHEAD LIGHT FIXTURES THAT HAVE BROKEN FREE AND ARE HANGING LOOSE AND ARE A POTENTIAL LIFE SAFETY ISSUE.

FBC(2014) 116.2.1.2.2

1. THERE ARE SEVERAL AREAS THROUGHOUT THE BUILDING WHERE THERE IS SIGNIFICATE DETERIORATION OF THE CONCRETE COLUMNS, CONCRETE BEAMS, AND CONCRETE WALKWAYS WHERE REBAR IS EXPOSED. THIS DETERIORATION HAS COMPROMISED THE STRUCTURAL INTEGRITY OF THIS BUILDING CAUSING POTENTIAL LIFE SAFETY ISSUES.

FBC(2014) 116.2.1.3.1

1. THERE IS AN ILLEGAL GAS LINE INSTALLED ON THE NORTH SIDE OF THE BUILDING. THIS ILLEGAL GAS LINE WAS INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS. THE GAS LINE IS BLOCKING TWO DOORS MAKING THEM UNABLE TO BE OPENED.

2. THERE ARE MULTIPLE UNITS THAT ARE IN THE PROCESS OF BEING REMODELED. THIS WORK INCLUDES BUT IS NOT LIMITED TO THE DEMOLITION OF KITCHENS AND BATHROOMS, PLUMBING, ELECTRICAL AND STRUCTURAL WORK BEING DONE. THIS WORK HAS COMMENCED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

._____

CASE NO: CE15080318

CASE ADDR: 4040 GALT OCEAN DR # 619

OWNER: WENKING LLC INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE REMOVAL, REFINISHING, ALTERATION, AND REPLACEMENT OF THIS FRONT ENTRY DOOR WITHOUT THE REQUIRED PERMIT AND OR INSPECTIONS. THIS DOOR IS NOT A FIRE RATED DOOR. THIS ISSUE WAS ALSO ADDRESSED BY THE

F.L.F.D.

FBC(2014) 109.3.3

THIS CODE CASE WILL REQUIRE AN A.T.F. PERMIT BE OBTAINED AND DOUBLE FEES WILL APPLY.

FBC(2014) 110.6

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND DOUBLE PERMIT FEES WILL APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE15080670

CASE ADDR: 200 S BIRCH RD # 506

OWNER: GAVULA, WALTER INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2014) 105.1

THIS CONDO UNIT HAS BEEN COMPLETELY REMODELLED TO INCLUDE BUT IS NOT LIMITED TO:

- 1. FULL KITCHEN REMODEL.
- 2. KITCHEN CEILING FRAMED.
- 3. DRYWALL.
- 4. LIGHTING INSTALLED.
- 5. CLOSET BUILT FOR WASHER AND DRYER UNITS.
- 6. WINDOWS AND GLASS DOOR REPLACED.
- 7. ELECTRICAL PANEL REPLACED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.4

THIS CONDO UNIT HAS BEEN COMPLETELY REMODELLED TO INCLUDE BUT IS NOT LIMITED TO:

1. PLUMBING FIXTURES AND WATER HEATER ARE BEING REMOVED AND REPLACED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.5

THIS CONDO UNIT HAS BEEN COMPLETELY REMODELLED TO INCLUDE BUT IS NOT LIMITED TO:

1. ELECTRICAL PANEL BEING REMOVED AND REPLACED WITH A NEWER GENERAL ELECTRIC PANEL. LIGHT FIXTURES ADDED IN THE CEILING OF BOTH THE KITCHEN AND BATHROOM WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2014) 105.3.1.4.11

THIS CONDO UNIT HAS BEEN COMPLETELY REMODELLED TO INCLUDE BUT IS NOT LIMITED TO:

1. THE INSTALLATION OF A WASHER AND DRYER WITHOUT THE REQUIRED MECHANICAL PERMIT AND/OR INSPECTIONS.

FBC(2014) 107.1.1

THE SEVERITY OF THIS CODE CASE AND THE WORK THAT WAS DONE AND THE BUILDING CODE VIOLATIONS THAT EXIST WILL REQUIRE PLANS PROVIDED BY A DESIGN PROFESSIONAL BEING EITHER A STATE OF FLORIDA LICENSED ARCHITECT OR ENGINEER TO DOCUMENT THE VIOLATIONS AND CORRECTIONS THAT NEED TO BE MADE TO BRING THIS CONDO UNIT INTO COMPLIANCE.

FBC(2014) 109.3.3

THIS CODE CASE WILL REQUIRE ALL PERMITS TO BE DOUBLE FEE.

FBC(2014) 110.6

THE CONDO UNIT OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE A.T.F. PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

CASE NO: CE13051997
CASE ADDR: 1515 NW 7 AVE
OWNER: FOUNDATION TRUST

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THE SINGLE FAMILY DWELLING HAS BEEN ALTERED IN THE FOLLOWING MANNER WITHOUT A PERMIT:

- 1. NEW WINDOWS HAVE BEEN INSTALLED.
- 2. A KITCHEN REMODELING PROJECT IS IN PROGRESS.
- 3. A BATHROOM REMODELING PROJECT IS IN PROGRESS.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM HAS BEEN ALTERED BY THE KITCHEN AND BATHROOM REMODELING WITHOUT A PERMIT.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM HAS BEEN ALTERED WITH THE KITCHEN AND BATHROOM REMODELING WITHOUT A PERMIT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14031507 CASE ADDR: 416 SW 11 CT

OWNER: REYNOLDS, STUART L

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

- 1. THE PROPERTY OWNER HAS CONVERTED THIS SINGLE FAMILY HOUSE INTO A DUPLEX RENTING OUT THE BACK AND FRONT TO TWO DIFFERENT FAMILIES. THEY HAVE ENCLOSED THE CARPORT AND HALLWAY LEADING TO ONE PART OF THE HOUSE TO CREATE THE NEW FLOOR PLAN.
- 2. THEY HAVE ADDED ELECTRIC OUTLETS AND PLUMBING FIXTURES IN THE ENCLOSED CARPORT.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

THE USE AND THE OCCUPANCY OF THE CARPORT HAS BEEN CHANGED FROM THE ORIGINALLY PERMITTED OCCUPANCY CLASSIFICATION CLASS U (UTILITY) TO R-3 (LIVING SPACE) WITHOUT OBTAINING THE REQUIRED PERMITS AND THE CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

CASE NO: CE14050340
CASE ADDR: 820 NE 16 TER
OWNER: SILVERMAN, MARC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

1. KITCHEN REMODELLED WITHOUT THE REQUIRED PERMITS OR INSPECTIONS.

2. THE FRONT PORCH DOES NOT HAVE A PERMIT.

CASE NO: CE14051438 CASE ADDR: 645 NW 14 TER

OWNER: 645 NW 14 TERRACE LANDTRUST

SWITZER, STAN TRSTEE

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS, AS FOLLOWS:

- 1. THIS PROPERTY WAS UPGRADED. THE INTERIOR WAS REMODELED WITH NEW CABINETS INSTALLED IN THE KITCHEN AND BATHROOM AREAS.
- 2. NEW ELECTRICAL AND PLUMBING FIXTURES ALSO WERE INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15060134
CASE ADDR: 2601 SW 13 PL
OWNER: HSBC BANK USA NA

%OCWEN LOAN SERVICING LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS FOR WORK IN PROGRESS:

- 1. INSTALLING WOOD FENCE.
- 2. REBUILDING FRONT WITH PORCH (ROOF) OVERHANG.
- 3. WOOD SIDING WORK AT THE REAR OF THE DWELLING AND STRUCTURAL WORK AROUND THE WINDOWS.
- 4. THIS DWELLING WAS DAMAGED BY A FIRE ON SEPTEMBER 30, 2002 AS PER CASE CE02100033. THERE ARE NO PERMITS ON RECORD TO PERFORM AND RESTORE WORK AFTER THE FIRE.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT OBTAINING THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15060308 CASE ADDR: 1239 NE 5 AVE

OWNER: PREF 1239 NE 5TH AVE

FT LAUDERDALE LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. INTERIOR ALTERATIONS WERE DONE IN THE KITCHEN AND BATHROOM AREAS. THEY WERE UPGRADED WITH NEW CABINETRIES, PLUMBING AND ELECTRICAL FIXTURES.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. PLUMBING ALTERATIONS IN THE KITCHEN AND BATHROOMS.
- 2. THE WATER PUMP FOR THE WELL WAS REPLACED.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. ALTERATIONS THAT WERE DONE TO THE ELECTRICAL SYSTEM TO REMODEL THE KITCHEN AND BATHROOM MUST MEET THE NEC 208.10.

N.E.C. 208.10 - ELECTRIC OUTLETS IN THE KITCHEN AND BATHROOM AREAS. WHEN REPLACING KITCHEN CABINETS, ALL THE ELECTRIC OUTLETS IN THE CABINETS COUNTER TOP'S BACK SPLASH IS TO BE BROUGHT UP TO MEET THE NEW CODE FOR SPACING AND CIRCUITRY.

FBC(2010) 105.4.11

A MECHANICAL SYSTEM WAS INSTALLED IN THE FACILITY WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER:

1. A DUCTED CENTRAL A/C WITH 7.5 KW ELECTRICAL HEATERS WAS INSTALLED IN THE DWELLING. BY THIS ACTION THE OWNER IS INCREASING THE AMPERAGES LOAD IN THE MAIN ELECTRICAL PANEL OVER THE TOTAL AMPS LOAD RATED THAT WAS PERMITTED. IT HAS BECOME AN ELECTRICAL FIRE HAZARD.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14071684
CASE ADDR: 1608 SW 10 CT
OWNER: SOFREI LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. INTERIOR ALTERATIONS OF THE ELECTRICAL, PLUMBING AND MECHANICAL SYSTEMS.
- 2. DRYWALL REPLACEMENT INSIDE THE KITCHEN AND BATHROOMS AREAS.
- 3. THE WINDOWS AND EXTERIOR DOORS WERE REPLACED.
- 4. THE PROPERTY WAS RE-ROOFED WITH SHINGLES. THE PERMIT WAS LEFT TO EXPIRE WITHOUT PASSING FINAL INSPECTIONS. TODAY IT REMAINS WORK WITHOUT PERMITS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REOUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14090304 CASE ADDR: 720 BAYSHORE DR

OWNER: NAUTICAL TOWERS CONDO ASSN INC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF DRYWALL IN THE COMMON AREA

CLUBHOUSE/MEETING ROOM.

CASE NO: CE15071515 CASE ADDR: 1135 NW 7 AV

TIITF/HRS-YOUTH SERV OWNER:

BROWARD CHILDRENS SHELTER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2014) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

1. ALL WORK AND CORRECTIONS REQUIRING PERMITTING MUST COMPLY WITH THIS SECTION OF THE CODED.

FBC(2014) 110.6

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2014) 1003.6

WINDOWS AND DOORS HAVE BEEN BLOCKED LIMITING EGRESS AS REQUIRED BY CODE.

FBC(2014) 1006.1

EMERGENCY EXIT LIGHTS MUST BE MADE FUNCTIONAL AS REQUIRED BY CODE.

FBC(2014) 1006.3

EMERGENCY EXIT LIGHTS MUST BE MADE FUNCTIONAL AS REQUIRED BY CODE.

FBC(2014) 1008.1.9.1

ALL DOORS MUST HAVE LATCHES AND HANDLES AS TO BE ABLE TO BE OPENED FROM THE INTERIOR OF THE FLOOR AREA THEY SERVICE AS REQUIRED BY CODE.

FBC(2014) 1008.1.9.3 4.

DOUBLE KEYED DEAD BOLTS MUST BE REMOVED AS THEY PREVENT EGRESS FROM THE FLOOR AREA THEY SERVE AS REQUIRED BY CODE.

FBC(2014) 1029.1

ALL ROOMS THAT ARE DESIGNED WITH WINDOWS THAT CAN SERVE AS A MEANS OF EGRESS MUST HAVE AT MINIMUM ONE WINDOW UNBLOCKED AS TO SERVE AS THE SECONDARY MEANS OF EGRESS AS REQUIRED BY CODE.

FBC(2014) 1522.3.4

NO WIRE SHALL BE WITHIN THE PHYSICAL LIMITS IDENTIFIED BY THE SECTION OF THIS CODE.

NEC 110.26

WORKING SPACE AROUND PANELS MUST MEET THIS SECTION OF THE CODE.

NEC(2005) 110.12

ALL UNSUSED OPENING IN ELECTRICAL PANELS MUST BE SEALED.

NEC(2005) 110.22

ALL PANELS AND MEANS OF DISCONNECT MUST BE IDENTIFIED AND LABELED IDENTIFYING THE CIRCUITS THEY SERVE.

NEC(2005) 110.27

ALL ENERGIZED CONNECTIONS MUST BE GUARDED FROM UNAUTHORIZED CONTACT.

NEC(2005) 210.8

AREAS REQUIRING GFI PROTECTION ON THE EXTERIOR AND WET KITCHEN AND BATHROOM AREA MUST BE MADE OPERABLE.

NEC(2005) 230.24

PANEL CANNOT BE BLOCKED AND MUST BE MADE ACCESSIBLE FOR EMERGENCY DISCONNECT IF REQUIRED.

NEC(2005) 406.11

DWELLING UNITS MUST HAVE TAMPER-RESISTANT RECEPTACLES.

NEC(2005) 408.38

ALL PANELS DISCONNECT BOXES MUST BE SECURED AS TO NOT HAVE ACCESS TO ENERGIZED CONNECTIONS OR HAVE A DEAD FRONT COVER.

NEC(2005) 408.4

ALL PANELS AND MEANS OF DISCONNECT MUST BE IDENTIFIED AND LABELED IDENTIFYING THE CIRCUITS THEY SERVE.

NEC(2005) 440.22(A)

CIRCUIT/FUSE/BREAKER MUST BE COMPATIBLE AND BE ABLE TO CARRY THE LOAD OF THE MECHANICAL EQUIPMENT THEY SERVE.

NEC(2005) 440.22(C)

CIRCUITS MUST MEET MANUFACTURERS CRITERIA.

CASE NO: CE15040367 CASE ADDR: 2020 NW 28 AVE

OWNER: RHA 2 LLC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

1. A CHAIN LINK FENCE HAS BEEN ERECTED AROUND THE PARKING LOT WITHOUT THE PROPER PERMIT OR MEETING THE REQUIREMENTS OF: FBC 2224.2 CHAIN LINK FENCES LESS THAN 12 FEET (3.7 M) IN HEIGHT SHALL BE DESIGNED ACCORDING TO THE LOADS SPECIFIED IN CHAPTER 16 (HIGH-VELOCITY HURRICANE ZONES).

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15040774
CASE ADDR: 208 SW 2 ST
OWNER: OLIVA OLIVA LLC

A I R ENTERPRISES LLC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

1. STRUCTURAL, PLUMBING AND ELECTRICAL ALTERATIONS WERE DONE TO BUILD A WOOD SHED TO HOUSE THE ICEMAKER AND A COOLING SYSTEM THAT WAS INSTALLED AT THE FRONT OF THE STORE. BOTH WITHOUT THE APPROVAL OF THE BUILDING AND FIRE DEPARTMENTS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15041593
CASE ADDR: 1645 NE 12 ST
OWNER: MINGER, WILLIAM J
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

- 1. STRUCTURAL WORK IN PROGRESS. THE OPENING FACES THE CARPORT.
- 2. THE WINDOWS WERE REMOVED AND GLASS BLOCKS ARE BEING PLACED ON THEM.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

HEARING TO IMPOSE FINES

CHAPTER 11, FORT LAUDERDALE CODE OF ORDINANCES

CASE NO: CE13091180 CASE ADDR: 833 NW 19 AV

OWNER: BROWN, J M & SILLIE MAE EST

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

1. WINDOWS AND DOORS ARE BEING REPLACED.

2. A/C UNIT WAS REPLACED.

3. ELECTRICAL WORK DONE. DISCONNECTED BOX TO THE $^{\lambda/C}$

4. PLUMBING WORK DONE. A DRAIN LINE WAS EXPOSED ON THE NORTH SIDE OF THE HOUSE DRAINING ONTO THE GROUND.

FBC(2010) 105.4.4

PLUMBING INSTALLED AND EXPOSED ON NORTH SIDE OF HOUSE AND DRAINING ONTO THE GROUND WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.5

ELECTRICAL WORK INSTALLED, DISCONNECT TO A/C WITHOUT THE REQUIRED PERMIT OR INSPECTIONS.

FBC(2010) 105.4.15

WINDOWS AND DOORS INSTALLED WITHOUT THE REQUIRED

PERMIT OR INSPECTIONS.

._____

CASE NO: CE14060058

CASE ADDR: 2500 LUCILLE DR

OWNER: KLAIRMONT, LARRY

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THERE ARE SEVERAL ITEMS THAT HAVE BEEN INSTALLED ON THIS PROPERTY WITHOUT FIRST OBTAINING THE

REQUIRED PERMITS TO INCLUDE:

A SMALL SHED.
 A GENERATOR.
 AN AWNING.
 A POOL HEATER.

CASE NO: CE14061007 CASE ADDR: 2186 NE 59 CT

OWNER: O FLAHERTY, DANIEL

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH AN INTERIOR REMODEL WITHOUT THE REQUIRED PERMITS AND/OR

INSPECTIONS.

FBC(2010) 105.4.15

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF WINDOWS AND DOORS WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.17

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE GARAGE DOOR WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE PROPERTY OWNER WILL BE REQUIRED TO OBTAIN ALL REQUIRED PERMITS, PASS THE ATF PLAN REVIEW AND PAY DOUBLE PERMIT FEES THAT MAY APPLY. SCHEDULE AND PASS ALL REQUIRED INSPECTIONS AND PROPERLY CLOSE ALL REQUIRED PERMITS BEFORE THIS CODE CASE IS FULLY COMPLIED AND CLOSED.

._____

CASE NO: CE14091251
CASE ADDR: 1736 SE 14 ST
OWNER: VERDUGO, CARLOS E
INSPECTOR: ROBERT MASULA

VIOLATIONS: 9-280(b)

- 1. THERE ARE BUILDING PARTS WHICH ARE DETERIORATED AND NOT MAINTAINED.
- 2. THE SEAWALL AT THIS PROPERTY IS IN NEED OF REPAIRS AND MAINTENANCE.

FBC(2010) 105.4.3

- 1. THIS PROPERTY HAS BEEN ALTERED WITH THE PARTIAL DEMOLITION OF A DOCK WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.
- 2. THE WOODEN DOCK HAS NOT BEEN MAINTAINED AND HAS NOW DETERIORATED FROM THE ELEMENTS. THIS STRUCTURE HAS NOW BECOME A WINDSTORM HAZARD AND IS UNSAFE.

FBC(2010) 105.4.18

THIS PROPERTY HAS BEEN ALTERED WITH THE INSTALLATION OF A FENCE WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

CASE NO: CE14111609

CASE ADDR: 545 S FTL BEACH BLVD 1101

OWNER: WISMER, GERALD BRUCE

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR REMODELING WITHOUT THE REQUIRED STRUCTURAL PERMITS

AND/OR INSPECTIONS.

FBC(2010) 105.4.3

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INTERIOR DEMOLITION OF THE FRAMING AND DRYWALL THROUGHOUT THE KITCHEN, BATHROOMS, AND OTHER AREAS OF THIS UNIT WITHOUT THE REQUIRED DEMOLITION PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE REMOVAL OF THE PLUMBING FIXTURES IN THE KITCHEN AND BATHROOMS WITHOUT THE REQUIRED PLUMBING PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE ALTERATION OF ELECTRICAL WIRING AND DEVICES WITHOUT THE REQUIRED ELECTRICAL PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS CODE CASE WILL REQUIRE THAT ALL REQUIRED PERMITS ARE OBTAINED, INSPECTED, PASSED AND CLOSED IN ORDER TO COMPLY AND CLOSE THIS CODE CASE IN THIS CONDO BUILDING.

CASE NO: CE14121723
CASE ADDR: 2879 NE 28 ST
OWNER: NOLAN, GERALD N
INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS PROPERTY HAS BEEN ALTERED WITH THE SUB-DIVISION OF THE HOUSE TO CREATE SEPARATE RENTAL UNITS WITHOUT OBTAINING THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF PLUMBING FIXTURES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS PROPERTY HAS BEEN ALTERED BY ADDING ELECTRICAL WIRING, DEVICES AND FIXTURES WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS PROPERTY HAS BEEN ALTERED WITH THE REMOVAL AND REPLACEMENT OF THE MAIN A/C UNIT WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 110.9

THIS CODE CASE WILL REQUIRE THAT PERMITS BE OBTAINED, INSPECTED, PASSED AND CLOSED PRIOR TO COMPLYING AND CLOSING THIS CASE.

FBC(2010) 111.1.1

THIS CODE CASE WILL REQUIRE A NEW CERTIFICATE OF OCCUPANCY IF THIS HOUSE IS SUBDIVIDED INTO SEPARATE RENTAL UNITS.

CASE NO: CE15020287

CASE ADDR: 3233 NE 34 ST # 1612 OWNER: CRICKETT, JOHN J

INSPECTOR: ROBERT MASULA

VIOLATIONS: FBC(2010) 105.1

THIS CONDO UNIT HAS BEEN ALTERED WITH THE STRUCTURAL WORK OF INTERIOR WALL FRAMING WITH REGULAR WHITE LUMBER (COMBUSTIBLE MATERIALS) AND DRYWALL INSTALLED WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.4

THIS CONDO UNIT HAS BEEN ALTERED WITH THE REMOVAL OF THE PLUMBING FIXTURES IN TWO BATHROOMS WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 105.4.5

THIS CONDO UNIT HAS BEEN ALTERED WITH THE DEMOLITION OF ELECTRICAL, THE ILLEGAL WIRING OF ROMEX WIRING INSTALLED, ELECTRICAL BOXES INSTALLED, ELECTRICAL WIRES CUT FROM INSIDE METAL CONDUIT AND ELECTRICAL ALTERATIONS WITHOUT THE REQUIRED PERMITS AND/OR INSPECTIONS.

FBC(2010) 105.4.11

THIS CONDO UNIT HAS BEEN ALTERED WITH THE INSTALLATION OF MECHANICAL DUCT WORK WITHOUT THE REQUIRED PERMIT AND/OR INSPECTIONS.

FBC(2010) 110.9

THE OWNER OF THIS CONDO UNIT WILL BE REQUIRED TO OBTAIN ARCHITECTURAL DRAWINGS BECAUSE OF THE SEVERITY OF THE VIOLATIONS, OBTAIN ALL REQUIRED PERMITS, SCHEDULE AND PASS ALL REQUIRED INSPECTIONS, PROPERLY CLOSE OUT ALL THE REQUIRED PERMITS IN ORDER TO FULLY COMPLY AND CLOSE THIS CODE CASE.

CASE NO: CE14031887
CASE ADDR: 1140 NW 4 AVE
OWNER: VILLA, ROBERT
INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS, INSPECTIONS AND THE CERTIFICATE OF OCCUPANCY FROM THE CITY BUILDING DEPARTMENT:

- 1. ONE SECTION OF THE GARAGE HAS BEEN ENCLOSED.
- 2. THE APPROVED USE HAS BEEN CHANGED TO A LIVING SPACE.
- 3. A DUCTED CENTRAL A/C WAS INSTALLED IN THE MAIN BUILDING.
- 4. THE WINDOWS WERE REPLACED AT THE REAR BUILDING (GARAGE).
- 5. ON THE FRONT OF THE MAIN BUILDINGS OPENINGS SOME WINDOWS WERE REPLACED.
- 6. AN OVERHANG ADDITION WAS BUILT AT THE REAR OF THE GARAGE TO COVER THE NEW WASHER AND DRYER AREA.

FBC(2010) 105.4.4

THE PLUMBING SYSTEM OF THE FACILITY HAS BEEN ALTERED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. PLUMBING ALTERATIONS WERE DONE TO BUILD A NEW KITCHEN AND BATHROOM INSIDE THE ENCLOSED SECTION OF THE GARAGE.
- 2. REAR LAUNDRY FACILITY WITH NEW WASTE PIPE, HOT AND COLD WATER SUPPLY PIPES WERE HOOKED-UP TO THE NEW PLUMBING FIXTURES.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

- 1. ALTERATIONS WERE DONE TO THE ELECTRICAL SYSTEM TO BUILD THE APARTMENT INSIDE THE GARAGE WITH NEW CIRCUITS FOR THE WINDOWS A/C, LIGHTS AND WALL OUTLETS, 220V POWER SUPPLY TO THE NEW KITCHEN AREA, CENTRAL A/C AND DRYER.
- 2. AT THE TIME OF MY INSPECTION, THERE WAS ELECTRICAL WORK IN PROGRESS AND BY HIS ACTIONS THE OWNER IS INCREASING THE AMPERAGE LOAD IN THE MAIN ELECTRICAL PANEL OVER THE TOTAL AMPS LOAD RATING THAT WAS PERMITTED. IT HAS BECOME AN ELECTRICAL FIRE HAZARD.

FBC(2010) 105.4.11

THE MECHANICAL SYSTEM OF THE FACILITY HAS BEEN CHANGED WITHOUT OBTAINING A PERMIT IN THE FOLLOWING MANNER, INCLUDING BUT NOT LIMITED TO:

1. A DUCTED CENTRAL A/C SYSTEM WITH 7.5 KW ELECTRICAL HEATERS WAS INSTALLED IN THE MAIN DWELLING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14051500 CASE ADDR: 1389 SW 24 AVE

OWNER: FIVE TEN FLORIDA III LLC

NEW OWNER: CSMA FT LLC %FIRST KEY MORTGAGE LLC

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

A NEW CASE HAS BEEN OPENED; SOME OF THE VIOLATIONS WERE REMOVED

- 1. THE WINDOWS AND DOORS REMAIN WITHOUT A PERMIT.
- 2. THE CENTRAL A/C WAS REPLACED.
- 3. THE KITCHEN AND THE BATHROOMS WERE UPGRADED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14080903

CASE ADDR: 320 DELAWARE AVE

OWNER: KOHUTH, RUSSELL THOMAS

% LLOYD H FALK

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS AND INSPECTIONS:

STOP WORK ISSUED.

- 1. THE NORTH WALLS FOOTING IS BEING REPAIRED.
- 2. FLOOR JOIST AND CEILING RAFTERS ARE BEING REPLACED.
- 3. THE EXISTING LIVING SPACE FLOOR LAYOUT IS BEING REDESIGNED WITH NEW FRAMING AND DRYWALL WORK.
- 4. A DUCTED CENTRAL A/C IS BEING INSTALLED.
- 5. INTERIOR ALTERATIONS OF THE ELECTRICAL AND PLUMBING SYSTEMS ARE BEING PERFORMED INSIDE THE DWELLING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 115.1

ALL WORK IN PROGRESS MUST BE STOPPED UNTIL THE ENTIRE REQUIRED PERMITS ARE ISSUED.

CASE NO: CE15041070
CASE ADDR: 1333 NE 15 AVE
OWNER: SPORN, KENNETH F &
DIMARIA, MARCELLO

INSPECTOR: GEORGE OLIVA

VIOLATIONS: FBC(2010) 105.11.2.1

THE FOLLOWING PERMITS WERE LEFT TO EXPIRE. THE POOL WAS FINISHED AND TODAY IT REMAINS WORK WITHOUT A PERMIT. THERE ARE ALSO LIFE SAFETY VIOLATIONS BECAUSE THE ELECTRICAL SYSTEM HAS NOT BEEN FINALLED AND THE CHILD BARRIERS HAVE NOT BEEN

APPROVED.

1. ELECTRICAL PERMIT #04120155 (EPOOL/SPAR)
2. BUILDING PERMIT #04120152 (BPOOL/SPAR)

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

.-----

CASE NO: CE15031104
CASE ADDR: 1531 NW 13 CT
OWNER: RHA 2 LLC
INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.4.18

CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE

REQUIRED PERMITS AND INSPECTIONS:

1. THE OLD CHAINLINK FENCE WAS REMOVED AND A NEW WOOD FENCE WAS INSTALLED.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

.-----

CASE NO: CE14081054

CASE ADDR: 1834 LAUD MANORS DR OWNER: WSC BRICKELL LLC

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS AS FOLLOWS:

- 1. WINDOWS AND EXTERIOR DOORS WERE REPLACED.
- 2. THE DWELLING WAS RE-ROOFED.
- 3. THE EXISTING CARPORT THAT WAS BUILT WITH THE DWELLING WAS ENCLOSED INTO A LIVING SPACE.
- 4. A DUCTED CENTRAL A/C WAS INSTALLED.
- 5. INTERIOR RENOVATIONS AND ELECTRICAL AND PLUMBING UPGRADES WERE PERFORMED INSIDE THE KITCHEN AND BATHROOMS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15040158

CASE ADDR: 400 ISLE OF CAPRI

OWNER: KUIJPER, MARTIJN PETER

INSPECTOR: JOSE ABIN

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

- 1. THE FOUR EXISTING AIR CONDITIONERS HAVE BEEN MOVED INTO THE EASEMENT WHICH IS LESS THAN TWO FEET FROM THE PROPERTY LINE.
- 2. POOL PUMPS AND CLEANING EQUIPMENT HAVE BEEN MOVED AND INSTALLED ON THE SOUTH SIDE OF HIS YARD.
- 3. A POOL AND SPA HEATER HAVE BEEN MOVED AND INSTALLED ON THE SOUTH SIDE OF HIS YARD.
- 4. A NEW GAS GENERATOR WITH NEW GAS LINES HAS BEEN INSTALLED ON THE SOUTH SIDE OF THIS YARD.
- 5. AN OUTDOOR KITCHEN HAS NOW BEEN ERECTED NEAR THE ORIGINAL LOCATION OF THE FOUR AIR CONDITIONERS. THIS CONSISTS OF THE CONSTRUCTION OF A CONCRETE OUTDOOR WALL APPROXIMATELY 12FT LONG AND 8FT TALL.
- 6. A NEW GAS LINE WAS MADE FOR THE GAS GRILL.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE14090224
CASE ADDR: 1619 NW 13 AVE

OWNER: RHA 2 LLC

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS, AS FOLLOW:

- 1. REROOF WORK IN PROGRESS.
- 2. THIS PROPERTY HAS BEEN UPGRADED. STOP WORK ISSUED. THE INTERIOR WORK OR REMODEL IN PROGRESS WITH NEW CABINETS IN THE KITCHEN AND BATHROOMS AREAS.
- 3. NEW ELECTRICAL AND PLUMBING FIXTURES WERE INSTALLED.
- 4. THE WINDOWS WERE REPLACED IN THE OPENINGS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15031138

CASE ADDR: 1520 NW 4 ST

OWNER: FREEMAN, MARIA J

INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS:

1. BUILDING PERMIT 05080372 FOR NEW SINGLE FAMILY RESIDENCE IS EXPIRED. THIS DWELLING HAS BEEN OCCUPIED WITHOUT A FINAL INSPECTION AND C.O.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING AND INSPECTION PROCESS.

FBC(2010) 111.1.1

THIS SINGLE FAMILY DWELLING WITH A CLASSIFICATION R-3, IS BEING USED WITHOUT OBTAINING THE REQUIRED CERTIFICATE OF OCCUPANCY FROM THE BUILDING DEPARTMENT.

DEPARTMENT.

CASE NO: CE15040771
CASE ADDR: 201 SW 2 ST

OWNER: RIVERWALK CENTRE LTD INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED

PERMITS, INSPECTIONS AND C.O.

1. PLUMBING AND ELECTRICAL ALTERATIONS ARE BEING DONE TO BUILD A BAR INSIDE THE BUILDING.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT

THE PERMITTING AND INSPECTION PROCESS.

CASE NO: CE15060586 CASE ADDR: 1709 SW 10 ST

OWNER: SILVERA, KENNETH A
NEW OWNER: JAZBROWHOMES LLC
INSPECTOR: ALEJANDRO DELRIO

VIOLATIONS: FBC(2010) 105.1

THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. ILEGAL CONVERSION OF A SINGLE FAMILY DWELLING.
THE FLOOR PLAN HAS BEEN CHANGED BY ADDING NEW
ROOMS AND THE ELECTRICAL SYSTEM HAS BEEN ALTERED.

FBC(2010) 105.4.5

THE ELECTRICAL SYSTEM IN THIS BUILDING HAS BEEN ALTERED AND CONSTRUCTION WORK PERFORMED WITHOUT OBTAINING THE REQUIRED PERMITS AND INSPECTIONS IN THE FOLLOWING MANNER, BUT NOT LIMITED TO:

1. THERE IS ELECTRICAL WIRING EXPOSED THROUGHOUT THE HOUSE AND STAPLED ALONG THE DRYWALL TO HANG LIGHTING IN THE MAKE-SHIFT ROOMS.

FBC(2010) 110.9

THIS WORK IS IN PROGRESS OR IT HAS BEEN PERFORMED AND/OR COVERED-UP WITHOUT THE REQUIRED INSPECTIONS APPROVAL FROM THE BUILDING DEPARTMENT THROUGHOUT THE PERMITTING PROCESS.

FBC(2010) 111.1.1

MAKE-SHIFT ROOMS HAS BEEN ADDED TO THIS DWELLING ALTERING THE ORIGINAL USE AND MEANS OF EGRESS.